


03560.003434.



*Cofe*  
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	)	
	:	Examiner: A. He
SUSUMU YASUDA, et al.	)	
	:	Group Art Unit: 2858
Appl. No.: 10/798,315	)	
	:	
Filed: March 12, 2004	)	
	:	
For: ELECTRIC POTENTIAL SENSOR,	)	
AND IMAGE FORMING APPARATUS	:	
	)	
U.S. Patent No.: 6,965,239 B2	:	
	)	
Issued: November 15, 2005	:	August 23, 2006

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

REQUEST FOR  
CERTIFICATE OF CORRECTION  
UNDER RULES 322 AND 323

**Certificate**  
AUG 29 2006  
**of Correction**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

08/25/2006 TBESHAH1 00000097 6965239


01 FC:1811

100.00 OP

AUG 30 2006

Patentees' undersigned attorney may be reached in our Costa Mesa,  
California office by telephone at (714) 540-8700. All correspondence should continue to  
be directed to our address given below.

Respectfully submitted,

  
\_\_\_\_\_  
John D. Magluyan  
Attorney for Patentees  
Registration No.: 56,867

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
Facsimile: (212) 218-2200

CA\_MAIN 116891v1

Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,965,239 B2

DATED : November 15, 2005

INVENTOR(S) : Yasuda, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2:

Line 33, "with being" should read -- so as to be --.

COLUMN 5:

Line 39, "110a to 110d," should read -- 111a to 111d, --; and

Line 47, "with being" should read -- so as to be --.

COLUMN 6:

Line 62, "with being" should read -- so as to be --.

COLUMN 7:

Line 28, "assembly." should read -- assembly --.

COLUMN 8:

Line 13, "with" should read -- so as --; and

Line 14, "being" should read -- to be --.

COLUMN 11:

Line 3, "being to be" should read -- being placed so as --; and

Line 4, "placed" should read -- to be --.

CA\_MAIN 116889v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,965,239 B2

No. of add'l. copies  
@ 30¢ per page

Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,965,239 B2

DATED : November 15, 2005

INVENTOR(S) : Yasuda, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2:

Line 33, "with being" should read -- so as to be --.

COLUMN 5:

Line 39, "110a to 110d," should read -- 111a to 111d, --; and

Line 47, "with being" should read -- so as to be --.

COLUMN 6:

Line 62, "with being" should read -- so as to be --.

COLUMN 7:

Line 28, "assembly." should read -- assembly --.

COLUMN 8:

Line 13, "with" should read -- so as --; and

Line 14, "being" should read -- to be --.

COLUMN 11:

Line 3, "being to be" should read -- being placed so as --; and

Line 4, "placed" should read -- to be --.

CA\_MAIN-116889v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,965,239 B2

No. of add'l. copies  
@ 30¢ per page

AUG 30 2005

